



PARTS INFORMATION FROM DAEWOO HEAVY INDUSTRIES AMERICA CORPORATION

LIFT TRUCK SERIES:
GC20/25/30/32P-3

PT04-950908
April 29, 2003

For serial numbers beginning with:
DM, E1

SUBJECT: Improvement for Overheat Condition

You have been directed to this bulletin by ordering one of the following part numbers: **A221770, A221665, A221598, A221600, A221949, A221950, A221931, or A221916.**

For customers ordering either **A221770, A221665, A221598, or A221600** please read the history of the changed parts and please consider DHIAC's following recommendation:

History of Changed Parts

Trucks with serial number prefix of "E1" (Low Emission/LP Certified Engine): Battery Tray **A221770**, used in the Battery Group, was replaced by Battery Tray **A221949** and Muffler Tube **A221665**, used in the Muffler Group, was replaced by **A221950**. These changes, **together**, will provide an improved overheating condition apparent with this lift truck model.

Trucks with serial number prefix of "DM" (Standard LP Engine): Battery Tray **A221598**, used in the Battery Group, was replaced by Battery Tray **A221931** and Muffler Tube **A221600**, used in the Muffler Group, was replaced by **A221916**. These changes, **together**, will provide an improved overheating condition apparent with this lift truck model.

Recommendation

When replacing any of the old parts with their respective replacements, for the **first** time, it is recommended that you purchase **both** the new battery tray and the new muffler tube for the improvement to be effective. Please note that it is not necessary to replace both new parts at the same time, but it is **highly** recommended.