



Lift Truck Series:

D20~25~30~32[S-3]

D20~25~30~32~33[S-3]B3.3

G20~25~30[S-3]

G20~25~30~32[E-3TIER_II]

G20~25~30~32[E-3]

G20~25~30~32[P-3]

G20~25~30~32~33[P-3TIER_II]

GC20~25~30[S-3]

GC20~25~30~32[E-3TIER_II]

GC20~25~30~32[E-3]

GC20~25~30~32[P-3TIER_II]

GC20~25~30~32[P-3]

Bulletin # PT07-950937

Released November 11, 2005

Subject: 1.0 mm thickness shims

The 1.0 mm thick shims used in the Transmissions are no longer available.
Please use the following information to obtain proper replacements.

A213189 – Shim (1.0mm) ----→ replaced by 2 pcs A213190 Shim (0.5 mm)

A213185 – Shim (1.0mm) ----→ replaced by 2 pcs A213186 Shim (.05 mm)

(You will need to order the replacement shims 2 to 1 to get the right thickness)