DAEWOO

PARTS BULLETIN

PARTS INFORMATION FROM DAEWOO HEAVY INDUSTRIES AMERICA CORPORATION

Lift Truck Series: **PT08-950934**

B20~25~30[S-2] **May 11, 2004**

D20~25~30~32[S-3]
D35~40~45[S-2]
G20~25~30[S-3]
G20~25~30~32[E-3]
G20~25~30~32[P-3]

Subject: A212161 Shim

Due to a field problem encountered with this shim **A212161** , it has been replaced by 2 other shims. The New shim part numbers are **A231884 & A231885**. The thickness of the new shims are **A231884 (1.0mm) and A231885 (0.5 mm)**. The new shims require no bolts to retain them, They are held in place by the stub shaft at the axle pivot point. Please order as required to obtain the proper clearance specifications as required in the Service Manual Procedures.

gls