



DAEWOO

PARTS BULLETIN



PARTS INFORMATION FROM DAEWOO HEAVY INDUSTRIES AMERICA CORPORATION

Lift Truck Series:

PT12-950987

D20/25/30/32S-3, G20/25/30/32/33P-3,
G20/25/30/32E-3, GC20/25/30/32P-3

Subject: A215228 & A215229 Control Valve Availability / Changeover.

Due to a shortage of raw materials needed to manufacture the above mentioned Control Valves, DHIAC is forced to phase out the Valve assemblies, as well as the individual valve sections. There are various parts and pieces still available in our Parts stock. Please continue to utilize the "Self Help" tool found on the Lift Truck On Line Parts Book main page to determine serviceability of your current valve. Only after the components have been depleted, should you replace the assembly.
(The related seal kits will remain serviceable)

Please refer to the following chart for changeover information:

	To replace 3-Section Valve (A215228) use this chart			To replace 4-Section Valve (A215229) use this chart				
D20/25/30/32S-3 (S/N 90-XXXX)	A215270- New C/V	A212915- Tube 1ea	A212916- Tube 1ea	A215271- New C/V	A212915- Tube 1ea	A212916- Tube 1ea	A212919- Tube 1ea	A212920- Tube 1ea
G20/25/30/32/33P-3 (S/N's D2, DZ, GB, GQ, GC, GR)	A215270- New C/V	A212913- Tube 1ea	A212914- Tube 1ea	A215271- New C/V	A212913- Tube 1ea	A212914- Tube 1ea	A212917- Tube 1ea	A212918- Tube 1ea
G20/20/30/32E-3 (S/N's CW, CX, DX)	A215270- New C/V	A212913- Tube 1ea	A212914- Tube 1ea	A215271- New C/V	A212913- Tube 1ea	A212914- Tube 1ea	A212917- Tube 1ea	A212918- Tube 1ea
GC20/25/30/32P-3 (S/N's DM & E1)	A215270- New C/V	A225141- Tube 1ea	A225142- Tube 1ea	A215271- New C/V	A225141- Tube 1ea	A225142- Tube 1ea	A225143- Tube 1ea	A225144- Tube 1ea