



LIFT TRUCK SERIES:
GC15/18/20C

PT13-950906

SUBJECT: D510024 U-PACKING

This part was listed in the GC15/18/20C parts book for NHL = D144202 (Cylinder gp – sideshifter) by mistake. The entire break-down for this group in the GC15/18/20C parts book is wrong. This part is not a component of that group. For the correct service bill of material please call. This is still a valid service part in other applications.